- Absorbing State
  - Simple Triplex System with fail-stop behavior
  - Assumptions:
    - » no repair
    - » perfect fault coverage
      - recall: fault coverage is a measure of the systems ability to detect faults and recover
    - » homogeneous components
    - » independent failures

© 2011 A.W. Krings

Page: 1

CS449/549 Fault-Tolerant Systems Sequence 10

## Markov Models of Typical Systems

- System with Repair
  - Simple Triplex System with fail-stop behavior and repair
  - Same assumptions as previous example

- Fault Coverage
  - Simple Triplex System
  - Fault Coverage
    - $\sim C$  = probability that fault is properly handled
    - »  $C_i$  has major impact on reliability

© 2011 A.W. Krings

Page: 3

CS449/549 Fault-Tolerant Systems Sequence 10

# Markov Models of Typical Systems

- Multiple Faults
  - Simple Triplex System with double fault

 $t_r = \text{recovery time from fault}$ 

 $\rho = \frac{1}{t_{\cdot}} \quad \text{recovery rate}$ 

- Simple Triplex System with double fault (cont.)

© 2011 A.W. Krings

Page: 5

CS449/549 Fault-Tolerant Systems Sequence 10

## Markov Models of Typical Systems

- Different λ's
  - e.g. hot + cold spares
    - » typical MTTF(cold) = 10 MTTF(hot)
  - notation: h.c
    - h = number of hots
    - c = number of colds
  - assume perfect coverage
  - assume switching mechanism

- Passive TMR with 2 Failure Modes
  - fail passive => processor just disconnects
  - notation: n.f
    - » n = number of non-faulty processors running
    - » f = number of faulty processors running
  - assume different fail rates
    - » failure mode 1: benign fail rate  $\lambda_{stop}$
    - » failure mode 2: single non-benign fail rate  $\lambda_{err}$

© 2011 A.W. Krings

Page: 7

CS449/549 Fault-Tolerant Systems Sequence 10

## Markov Models of Typical Systems

- Passive TMR with 2 Failure Modes (cont.)

© 2011 A.W. Krings

Page: 8

CS449/549 Fault-Tolerant Systems Sequence 10

## Sharpe & Markov Chains

Here we used SHARPE to determine the unreliabilities.

The main slide of interest is the last one that contains the probabilities of being in the specific states.

Why is this interesting? Well...

© 2011 A.W. Krings

Page: 9

CS449/549 Fault-Tolerant Systems Sequence 10

### Sharpe & Markov Chains

- SHARPE extracts model and analysis type:
  - Cyclic vs. Acyclic Model
  - Steady-State vs. Transient Analysis

```
markov model_name
{param_list}

from to transition_rate

<name name expression>
end

initial state probabilities

<name expression>
end
```

© 2011 A.W. Krings

Page: 10

CS449/549 Fault-Tolerant Systems Sequence 10

#### Markov Model

- P(0) = 0 is assumed for any state not listed in initialization
- The sum of all P(0) must be 1
  - » Beware of round-off errors
- Initial state probabilities section may be left empty if:
  - » Acyclic model with only 1 source state
    - Assumes P(0) = 1 for that state
  - » Irreducible model Steady State analysis
    - in this case initial conditions are irrelevant
- Advice: Always specify initial probabilities

© 2011 A.W. Krings

Page: 11

CS449/549 Fault-Tolerant Systems Sequence 10

### Useful functions

- tvalue ( t; model\_name, state; arg\_list )
  - Gives Transient Probabilities at time t.
  - If no state is given:
    - » computes transient prob. of being in an absorbing state at time t
    - » there can be more than one absorbing state
      - => prob. of being in any absorbing state.
  - If state is given:
    - » computes transient prob. of being in that state at time t

#### Useful functions

- prob ( model\_name, state {;arg\_list} )
  - Gives Steady State Probabilities (no time param)
  - Note: state parameter is not optional
  - With absorbing states this computes the steady state probability of ever visiting a specific state
  - If no absorbing states exist (irreducible chain), the steady state probability of being in a specified state is computed

© 2011 A.W. Krings

Page: 13

CS449/549 Fault-Tolerant Systems Sequence 10

### Interpretation of F(t)

- If a non-absorbing state is specified:
  - F(t) is the transient or steady state CDF for that state
- If an absorbing state is specified:
  - F(t) is the CDF to absorbing by that state
  - absorbing state normally indicates a specific failure mode
- If no state is specified:
  - F(t) is the CDF to include all absorbing states
  - i.e. it is the sum of all CDFs of individual absorbing states
  - e.g. indicating system failure

#### TMR example

TMR example

expr fail11 expr fail12 expr failrun expr failstop expr failall

END

© 2011 A.W. Krings

```
* SYSTEM: TMR_2MODE -- PASSIVE TMR WITH: FAIL-STOP AND FAIL-ACTIVE MODES
        * MODELS: MARKOV (ACYCLIC)
        * STATE NOTATION: "N.F" WHERE:
                 N == NUMBER OF NON-FAULTY PROCESSORS RUNNING.
                 F == NUMBER OF FAULTY PROCESSORS STILL RUNNING.
              ----- MODEL DEFINITIONS
        MARKOV tmr_2mode
         3.0 2.0 3*LAMstop
         3.0 2.1 3*LAMerr
         2.0 1.0 2*LAMstop
         2.0 1.1 2*LAMerr
         2.1 2.0 1*LAMstop
         2.1 1.1 2*LAMstop
         2.1 1.2 2*LAMerr
         1.0 0.0 1*LAMstop
         1.0 0.1 1*LAMerr
        END
                    ----- INITIAL CONDITIONS (START IN 3.0)
         3.0 1.00
        END
© 2011 A.W. Krings
                                     Page: 15
                                                              CS449/549 Fault-Tolerant Systems Sequence 10
```

#### ----- PARAMETER BINDING **BIND** LAMBDA 1\*10^-4 LAMstop 0.9\*LAMBDA LAMerr 0.1\*LAMBDA **END** ----- ANALYSES AND EVALUATIONS cdf (tmr\_2mode) cdf (tmr\_2mode,0.0) var fail01 value(100.0;tmr\_2mode,0.1) var fail11 value(100.0;tmr 2mode,1.1) var fail12 value(100.0;tmr\_2mode,1.2) var failrun fail01 + fail11 + fail12 var failstop value(100.0;tmr\_2mode,0.0) var failall failrun + failstop expr fail01

CS449/549 Fault-Tolerant Systems Sequence 10

Page: 16

## TMR example

#### CDF for system tmr\_2mode:

1.0000e+00 t( 0) exp( 0.0000e+00 t) +-3.0526e+00 t( 0) exp(-1.0000e-04 t) + 3.2222e+00 t( 0) exp(-2.0000e-04 t)

conditional CDF for time of reaching this absorbing state

+ -1.1696e+00 t( 0) exp(-2.9000e-04 t)

mean: 1.8448e+04 variance: 1.3689e+08

© 2011 A.W. Krings Page: 17 CS449/549 Fault-Tolerant Systems Sequence 10

failall: 5.6778e-05